

Grela Well Drilling, Inc.
143 Main Street
Terryville, Ct 06786
(860) 583-3237 **1-800-890-9234** **Fax (860) 582-6335**
www.grelawelldrilling.com

WELL RECOVERY TEST

The well recovery test done November 10, 2020 by George Grela Jr. V.P indicated the well has a yield of 10 gallon per minute at the time of the recovery test.

Name: Larry Farrell Job Location: 130 Johnnycake Mt Rd Burlington

Email: buildingofficial@burlingtonct.us Mailing Address: 200 Spielman Highway Burlington CT 06013

WELL INFORMATION

Drilled: Yes Hand Dug: N/A Tile & Cover: N/A Water Tight Cap: Yes

Pitless Adapter: Yes Casing Size: 6" Depth: 250'? Septic or Sewer: Septic

Pump Setting: 240'? Type of Pump: submersible Horsepower: 1 hp 2 wire pump

Pump tech: N/A Amps: 9 Voltage: 220V

Well location: In flowers surrounding flag pole

TANK INFORMATION

Type of Tank: Bladder Tank Model: Challenger Size: 44 gallon Relief Valve: yes

Water Logged? New

WATER TREATMENT: No water treatment on site

RECOVERY TEST RESULTS

Well Recovery: 10

Time Test Began: 9:10 a.m Time Test Ended: 10:12 a.m

Total Gallons Pumped Out: 660'

Static Level at the Beginning of the test: 26' Static Level at the End: 130'

WATER TESTS

Were any water tests taken? No, none requested

COMMENTS: Well meets the State of Connecticut guidelines for well production.

*Please note the results stated in this report pertain only to that date and time when the test was actually performed. Many factors exist which may cause the recovery rate and static level of a well to change subsequent to the date of taking the test. No warranty or representation whatsoever is made pertaining to the results of the test performed as such relates to any further time.

Customer Signature: CUSTOMER SIGNATURE ON FILE